FITNESS CERTIFICATE

To be fiiled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1.	Name of the Officer	Saffer . S						
2.	Name of the School							
3.	Location with name of Education District/ Sub. District	K.E. CARMEL CENTRAL SCHOOL						
4.		Muhamma Alappuzha						
4,	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Seperate sheet attached:						
5.	Period for which the certificate is issued	10.45-26 At 1-1-						
6.	Nature of defects, if any	2025-26 Accademic year.						
0.	a) Foundation and basement	7						
	b) Superstructure) NIL.						
	c) Doors and Windows							
	d) Wood work wrought and put up	W.1'						
	e) Roof							
	f) Flooring							
_	g) Miscellaneous (Cracks, etc.)							
7.	Any major defects noticed which will render the building unsafe in any manner	N.V.						
8.	Whether maintenance works have been done properly	V. 7						
9. I	Whether the structure is sound or not for conducting classes Note: 1. The stability of the structure should be examined als exposure of flood etc. 2. Any additional observations if dec separately with this certificate.	Sound for Wyne Wedyn o with reference to location, altitude, intensity of wind, med necessary for the certificate may be furnished						
	CERTIFIC	ATE						
certified that the school building was inspected by me on								
four	nd to be fit / unfit to conduct classes, for the period	on and						
	sons stated above.	2023 - 2026 for the						
leas	sons stated above.	2 .						
Place Date	(B () A	SAFEER S PEN-442649 OUT PU Assistant Evecutive Engineer SAFEER S PEN-442649 LSGD (LID& EW)						
500/8-6		Assistant Engineer						

Permanent Size with Height Year(2001)

Ground Floor (RCC Roof)

			~ **
1	Class room	640x640x370	9 Nos.
2	Class room	640x600x370	1 No.
3	Class room	640x649x370	2 Nos.
4	Class room	1222x671x370	1No.
5	Lab	640x998x370	1No.
6	Lab	640x971x370	1No.
7	Lab	887x671x370	1No.
8	Admission room	923x671x370	1No.
9	Sick room	600x671x370	1No.
10	Staff room	640x649x370	1No.
,	Store room	640x330x370	1No.
11	Councilor room	468x280x370	1No.
12	Vice principal room	468x277x370	1No.
13	7.00 p		, ,

First Floor (RCC Roof)

	Class room	640x640x370	8 Nos.
1	Class room	640x649x370	5 Nos.
2	Class room	622x671x370	1 No.
4	Lab	640x1245x370	1 No.
5	Exam cell	640x649x370	1 No.
6	Teachers room	905x671x370	1No.
7	Office room	1218x671x370	1 No.
8	Exam room	600x671x370	1 No.
9	Principal room	964x599x370	1 No.
10	Toilet	640x640x370	1 No.

Second Floor (Sheet Roofing with ceiling)

Second Floor (Sileer Rooming With Century)				
Class room	640x640x370	8 Nos.		
Class room	640x649x370	5 Nos.		
Class room	600x671x370	2 Nos.		
Class room	640x600x370	1 No.		
Class room	622x671x370	1 No.		
Room	600x671x370	1 No.		
Library	605x671x370	1 No.		
Lab	640x649x370	2 Nos.		
Toilet	640x640x370	1 No.		
Library	1627x572x370	1 No.		
	Class room Class room Class room Class room Class room Room Library Lab Toilet	Class room 640x640x370 Class room 640x649x370 Class room 600x671x370 Class room 640x600x370 Class room 622x671x370 Room 600x671x370 Library 605x671x370 Lab 640x649x370 Toilet 640x640x370		

Assistant Executive Enginee SAFEER .S

PEN - 442649
Assistant Executive Engineer
LSGD (LID& EW)

